


## Important

## Read This First

The N2865A USB Module is designed to work with DSO3000 Series oscilloscope firmware version 04.02.06 or higher. To upgrade your oscilloscope's firmware, please visit www.agilent.com/find/dso3000sw and follow the instructions. You can verify the firmware version by selecting "System Info" on the second page of your oscilloscope's Utility menu.

Upgrading requires a USB A->B cable, which is included with your DSO3000 Series oscilloscope.



Manual Part Number: N2865-92000, March 2007

